			Dart Aerospa	ace Ltd.	$\sim$
	nesday, 2/6/2008 10:25:22 AM Johnston	Process Sheet			8
Customer Job Number	: CU-DAR001 Dart Helicopters Services : 37247B	Drawing Name	: BASKET LID ASSEMBLY		
Estimate Number P.O. Number This Issue Prsht Rev First Issue Previous Run Written By Checked & Approv Comment		Part Number Drawing Number Project Number Prawing Revision Material Due Date  D  05-11-03 JLM	: D2989043 : D2989 REV B : N/A : B : : 2/18/2008 Qty:	·1 Um:	Each
Additional Product					
Job Number:	1 (44) 44 (4) (44) 4 (44) 4 (44) 4 (44) 4 (44)		<u> </u>		
Seq. #:	Machine Or Operation:	Description :			
1.0	D31821	Hinge			
Comme	ent: Qty.: 2.0000 Each(s)/Unit Total : Pick: Qty Part number Description Batch 2 D3182-1 Hinge	2.0000 Each(s)	E 05 04	25	
2.0	D34423	Shim			
Comme		2.0000 Each(s)	FC 08 00	135	
3.0	M304EX07516F	Expanded Metal Flat Stai			
Comme	ent: Qty.: 8.0000 sf(s)/Unit: Total: 8.00 Pick: QtyPart number Description Batch 2 8sf M304EX0.75-16F Expanded Metal	000 sf(s) M107316	FC 08	04 25	
4.0	M304TS0750W065	304 SQ Tube.75x.75x.065W			
Comme	ent: Qty.: 17.6400 f(s)/Unit_Total: 17.64	100 f(s)		m(12)	

Comment: Qty.: 17.6400 f(s)/Unit Total: 17.6400 f(s) 3/4" x 3/4" x 0.066" wall 304/316 SStubing.

Batch: 17.6400 f(s)/Unit Total: 17.6400 f(s)

FC 08 0425

## **Dart Aerospace Ltd**

Dait Ac	ospace	LIU							
W/O:			WC	RK ORDER CHANGES	)				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									·
,									
- <del>1</del>	<u> </u>								
Part No	:	PAR #:	Fault Cate	gory: N	NCR: Yes	No <b>DQ</b>	A:	Date: _	
					QA:	N/C Close	d:	_ Date: _	
NCR:		,	NORK ORD	ER NON-CONFORMAN	CE (NC	R)			
DATE	CTED	Description of NC		Corrective Action Section E		Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector
								:	
				•					
							•	1	-

NOTE: Date & initial all entries

Wednesday, 2/6/2008 10:25:22 AM Date: User:/ Kim Johnston **Process Sheet** Drawing Name: BASKET LID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D2989043 Job Number: 37247B Job Number: Description: Seq. #: Machine Or Operation: LARGE FABRICATION RESOURCE 1 5.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 1-Cut (4) D2236-1 From D3166-3 As Per Dwg D2989 Note: D2989-3/-4 On -041 Bom 2-Drill holes in tubing as D2989-043 per Dwg D2989 3-Deburr and remove all markings on material 4-Weld as per Dwg D2989 and D2989-043 Assembly using Welding Table and corner Jig. Deburr as Note: Expanded metal "diamonds" must run lengthwise. Eg 2.0" along length of lid VISUAL WELDING INSPECTION 6.0 QC9 Comment: VISUAL WELDING INSPECTION DIMENSIONAL CHECK 7.0 Comment: DIMENSIONAL CHECK 02909043 POWDER COATING 8.0 POWDER COATING M107550 Comment: POWDER COATING # 1 #2 1-Powder Coat White (Ref. 4.3.5.2) D2989-041 as per QSI 005 4.3 & Dwg D2989 INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 9.0 Comment: Inspect Powder Coat QC21 FINAL INSPECTION/W/O RELEASE 10.0 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

## **Dart Aerospace Ltd**

W/O:		WORK ORDER C	HANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			-				

Part No:	_PAR #:	Fault Category:	NCR: Yes	No	DQA:	Date:
			QA: N	/C C	losed:	Date:

	`	WORK ORD	ER NON-CONFORMAN	CE (NCR)			
	Description of NC		Corrective Action Section B				
STEP	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector
	·						
	STEP	STEP Description of NC	STEP Description of NC Section A Initial	STEP Description of NC Section A Initial Action Description	STEP Description of NC Section A Initial Action Description Sign &	STEP Section A Initial Action Description Sign & Section C	STEP Description of NC Section A Initial Action Description Sign & Verification Approval Chief Eng

NOTE: Date & initial all entries



DESIG	DS	DRAWN BY	DART AEROSPACE LT HAWKESBURY, ONTARIO, CANADA	D
CHEC	KED ./	APPROVED	DRAWING NO.	REV. B
	att	A THE	D2989 sh	EET 1 OF 3
DATE		I	TITLE	SCALE
05.0	6.07		BASKET LID ASSEMBLY	NTS
Α		00.10.27	NEW ISSUE	
В		05.06.07	ADD SHIM UNDER HINGES, UPDATE DIMENSIONS	LID

OS:08:19

## PARTS LIST:

Qty -041	Qty -043	Part Number	Description	
Х		D2989-041	BASKET LID ASSEMBLY (OUTSIDE)	
	Х	D2989-043	BASKET LID ASSEMBLY (INSIDE)	
	1	D2989-1	STRUT	
	1	D2989-2	STRUT	
	1	D2989-3	STRUT	
	1	D2989-4	STRUT	
	2	D2989-5	STRUT	
	2	D2989-7	STRUT	
1		D2989-9	STRUT	
1		D2989-10	STRUT	
1		D2989-11	STRUT	
1		D2989-12	STRUT	
2	<u> </u>	D2989-13	STRUT	
2		D2989-15	STRUT	
			·	
2		D2327-3	SPACER BUSHING	
1		D2506	LABEL PLATE	
2	2	D2989-17	STRUT (96.00" LONG)	
2		D2989-19	STRUT (31.19" LONG)	
1		D2512-7	STRUT SHUP C	OP'
2		D2581	MOUNTING BRACKET DELTA	NT
	2	D3182-1	HINGE	FRI
	2	D3442-3	SHIM	LLI

NOTES:

0.065 16 08.0206

SUBJECT TO AMENDMENT WITHOUT NOTICE

1) FRAME MATERIAL: AISI 304/316 SS, 3/4 x 3/4 x 0.060 WALL SQUARE TUBING WORK OR D2989-3/4/5/11/12/13 CAN BE MADE FROM D2236

2) MESH MATERIAL: 3/4-16F EXPANDED SS (REF DART SPEC M304EX0.75-16F)

3) WELD PER DART QSI 004

4) FINISH: POWDER COAT WHITE (REF. 4.3.5.2) PER DART QSI 005 4.3.
BLACK ANTI-SKID PAINT AS INDICATED PER DART QSI 005 4.4. SPRAY PAINT INSIDE SURFACE BLACK PRIOR TO APPLYING ANTI-SKID.

5) ALL DIMENSIONS ARE IN INCHES

5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

Copyright © 2000 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



